

Appendix 5

Woodwards Creek, Bungonia village

October 2011

In the last couple of years we have had very large erosion events, one of which was caused by two out of three pipes becoming blocked at the upper end of the creek in the village. This caused the water to be forced through the remaining open pipe at high velocity causing some of the erosion as seen in the following photos. The Park Trust has applied for a grant from the SCA to undertake a Management Plan to determine what the Trust can do to slow down this erosion.



The Park Trust obtained a grant from the SCA to develop a Management Plan, which is currently, January 2014, being developed by the NSW Soil Conservation Department.